



APPLE RUBBER PRODUCTS, INC. FIRST ARTICLE INSPECTION REPORT

CUSTOMERS NAME AND ADDRESS Customer XYZ			DATE: 5/16/2013				SHEET 1 OF 3						
			CUSTOMER ORDER NUMBER: PO123456										
			PART NUMBER: R00087-036-70SL										
			DESCRIPTION OF PART: O RING										
NUMBER OF SAMPLES 30			MOLD NUMBER: 1488				BLUEPRINT NUMBER: R00087-036-70SL			REV: A	DATE: 1/1/2017		
NUMBER OF CAVITIES: 102			COMPOUND: 17SL7AO				BATCH NUMBER: IM-32711						
GAGE	GRID	characteristic	cavity or piece number										
			1	2	3	4	5	6	7	8	9	10	
98-355	1	.087 +/- .005 ID	0.0843	0.0846	0.0843	0.0844	0.0840	0.0847	0.0847	0.0841	0.0840	0.0848	
98-355	2	.063 +/- .003 CS	0.0654	0.0651	0.0645	0.0653	0.0652	0.0646	0.0651	0.0647	0.0646	0.0650	

APPLE RUBBER PRODUCTS, INC.
 204 CEMETERY ROAD
 LANCASTER, N.Y. 14086
 N.Y. STATE: 716-684-6560
 TOLL FREE: 800-828-7745

NOTE: ALL DIMENSIONS OUT OF SPECIFICATION LIMITS MUST BE CIRCLED IN RED OR BOLD

ACCEPT

REJECT

SEND TO CUSTOMER FOR APPROVAL

MEASURED BY: A P.
 INITIALS

APPROVED BY: _____
 INITIALS

